

Inspection Photos
Location Name: Josh 21-4 4N46W
API Number: 125-09951



1. Well lease sign at wellhead.



2. View of wellhead.

Inspection Photos
Location Name: Josh 21-4 4N46W
API Number: 125-09951



3. View of repair work completed removing broken gauge.



4. Additional view of wellhead showing water leg disconnected from wellhead.