

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location ID: 418555

Date: 12/16/2024



Photo # 1196 Entrance to location

Photo # 1197 Location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location ID: 418555

Date: 12/16/2024



Photo # 1198 Location



Photo # 1209 Location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location ID: 418555

Date: 12/16/2024



Photo # 1210 Location



Photo # 1223 Location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location ID: 418555

Date: 12/16/2024



Photo # 1239 Location



Photo # 1259 NW corner of location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location ID: 418555

Date: 12/16/2024



Photo # 1260 NE corner of location



Photo # 1261 SW corner of location

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location ID: 418555

Date: 12/16/2024



Photo # 1263 SE corner of location



Photo # 1171 Insufficient tracking BMP's/tracking off location & onto to Mamm Creek Rd

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location ID: 418555

Date: 12/16/2024



**Photo # 1175 Insufficient tracking BMP's/tracking off location & onto to Mamm Creek Rd**




**Photo # 1180 Insufficient tracking BMP's/tracking off location & onto to Mamm Creek Rd**

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location ID: 418555

Date: 12/16/2024



**Photo # 1181 Insufficient tracking BMP's/tracking off location & onto to Mamm Creek Rd**

**Photo # 1182 Insufficient tracking BMP's/tracking off location & onto to Mamm Creek Rd**

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location ID: 418555

Date: 12/16/2024



**Photo # 1187 Insufficient tracking BMP's/tracking off location & onto to Mamm Creek Rd**



**Photo # 1188 Insufficient tracking BMP's/tracking off location & onto to Mamm Creek Rd**

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location ID: 418555

Date: 12/16/2024



Photo # 1212 Sign is becoming illegible




Photo # 1246 Tank label is weathered & some required information is illegible/does not comply with CECMC labeling rules

## Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC CB-TG Land NW 11D-20-692 Pad

Location ID: 418555

Date: 12/16/2024




Photo # 1243 Label is shows signs of disrepair



Photo # 1255 Debris