

Inspection Photos
Location Name: State 16-14
API Number: 125-09156



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: State 16-14
API Number: 125-09156



3. Gas meter inside meter shed.



4. Location overview.

Inspection Photos
Location Name: State 16-14
API Number: 125-09156



5. Erosion rilling and channeling starting at well area.



6. Erosion channeling at edge of location.

Inspection Photos
Location Name: State 16-14
API Number: 125-09156



7. Erosion channeling on access trail.



8. Erosion gully's cut into access trail.