

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0603-23-32

Location ID: 335647

Date: 12/17/2024



Photo # 1331 Location



Photo # 1333 Entrance to location

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0603-23-32

Location ID: 335647

Date: 12/17/2024



Photo # 1336 Location




Photo # 1339 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0603-23-32

Location ID: 335647

Date: 12/17/2024




Photo # 1340 Location



Photo # 1345 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0603-23-32

Location ID: 335647

Date: 12/17/2024



Dec 17, 2024 at 1:30:29 PM
+39.548919,-108.210364 ±2.63m
Parachute

Photo # 1346 Location



Dec 17, 2024 at 1:31:58 PM
+39.549134,-108.210110 ±2.81m
Parachute

Photo # 1348 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0603-23-32

Location ID: 335647

Date: 12/17/2024



Photo # 1341 Tank lacks required information/does not comply with CECMC labeling rules



Photo # 1343 Tank lacks required information/does not comply with CECMC labeling rules