

Inspection Photos

Location Name: QB Energy GMU 23-8C (H23NW) Pad

Location #: 335444



Photo # 4867 From entrance to location




Photo #4868 Location

Inspection Photos
Location Name: QB Energy GMU 23-8C (H23NW) Pad
Location #: 335444



Photo # 4869 Location



Photo # 4870 Location



Inspection Photos
Location Name: QB Energy GMU 23-8C (H23NW) Pad
Location #: 335444



Photo # 4871 Location



Photo # 4872 Location

Inspection Photos

Location Name: QB Energy GMU 23-8C (H23NW) Pad

Location #: 335444




Photo # 4873 PRV vent line on tank burner does not comply with CECMC pressure safety device rules