

Inspection Photos


Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0610-21-41

Location ID: 383264

Date: 12/17/2024



Dec 17, 2024 at 3:41:42 PM
+39.544559,-108.206065 ±5.20m
Parachute



Dec 17, 2024 at 3:58:15 PM
+39.544533,-108.206322 ±4.33m
Parachute

Photo # 1460 Entrance to location

Photo # 1482 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0610-21-41

Location ID: 383264

Date: 12/17/2024



Photo # 1461 Location



Photo # 1462 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0610-21-41

Location ID: 383264

Date: 12/17/2024



Photo # 1465 Location



Photo # 1472 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0610-21-41

Location ID: 383264

Date: 12/17/2024



Dec 17, 2024 at 3:52:06 PM
+39.544107,-108.206330 ±3.07m
Parachute

Photo # 1473 Location



Dec 17, 2024 at 3:57:28 PM
+39.544441,-108.206285 ±5.58m
Parachute

Photo # 1480 Location

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0610-21-41

Location ID: 383264

Date: 12/17/2024



Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0610-21-41

Location ID: 383264

Date: 12/17/2024



Photo # 1503 Location



Photo # 1510 NW corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0610-21-41

Location ID: 383264

Date: 12/17/2024



Photo # 1511 SW corner of location



Photo # 1513 SE corner of location

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0610-21-41

Location ID: 383264

Date: 12/17/2024



Dec 17, 2024 at 4:18:32 PM
+39.544632,-108.206162 ±2.35m
Parachute

Photo # 1514 NE corner of location



Dec 17, 2024 at 3:55:46 PM
+39.544180,-108.206171 ±2.83m

Photo # 1477 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0610-21-41

Location ID: 383264

Date: 12/17/2024



Photo # 1494 Tank heater PRV vent line does not comply with CECMC pressure safety device rules



Photo # 1505 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0610-21-41

Location ID: 383264

Date: 12/17/2024



Photo # 1507 Wildlife hazard



Photo # 1509 Wildlife hazard

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0610-21-41

Location ID: 383264

Date: 12/17/2024



Photo # 1467 Storage of Supplies and Equipment



Photo # 1469 Debris

Inspection Photos

Location: LARAMIE ENERGY LLC Cascade Creek (CC)/0610-21-41

Location ID: 383264

Date: 12/17/2024



Photo # 1471 Debris



Photo # 1479 Storage of Supplies and Equipment