

Inspection Photos

12/18/2024

Operator: CAERUS PICEANCE LLC 10456 (QB
ENERGY OPERATING LLC - 10844)

Location ID: 312584

Inspection Doc: 718100125

Mesa County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC 10456 (QB ENERGY OPERATING LLC - 10844)

Location ID: 312584



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC 10456 (QB ENERGY OPERATING LLC - 10844)

Location ID: 312584



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC 10456 (QB ENERGY OPERATING LLC - 10844)

Location ID: 312584



Photo 3: Photo example of areas that were visible. Vegetation that was apparent is predominantly desirable perennial species.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources