

Inspection Photos

12/18/2024

Operator: CAERUS PICEANCE LLC 10456 (QB
ENERGY OPERATING LLC - 10844)

Location ID: 312508

Inspection Doc: 718100127

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC 10456 (QB ENERGY OPERATING LLC - 10844)

Location ID: 312508



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC 10456 (QB ENERGY OPERATING LLC - 10844)

Location ID: 312508



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC 10456 (QB ENERGY OPERATING LLC - 10844)

Location ID: 312508



December 18, 2024



December 18, 2024

Photo 3: Additional reclamation efforts evident. Photos show hydromulch has been applied to the location, including the cut slopes.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources