

Inspection Photos

12/18/2024

Operator: ENCANA OIL & GAS (USA) INC
100185 / CAERUS PICEANCE LLC 10456 (QB
ENERGY OPERATING LLC - 10844)

Location ID: 423443

Inspection Doc: 718100129

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC 10456 (QB ENERGY OPERATING LLC - 10844)

Location ID: 423443



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview of the Location from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC 10456 (QB ENERGY OPERATING LLC - 10844)

Location ID: 423443



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC 10456 (QB ENERGY OPERATING LLC - 10844)

Location ID: 423443



Photo 3: Wildlife protection BMPs and container/tank labels have been maintained.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC 10456 (QB ENERGY OPERATING LLC - 10844)

Location ID: 423443



Photo 4: Wildlife protection BMPs and container/tank labels have been maintained.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC 10456 (QB ENERGY OPERATING LLC - 10844)

Location ID: 423443



December 18, 2024

Photo 5: Culvert at Location entrance has been maintained.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources