

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Production Pad

Location ID: 456107



Photo # 4898 From entrance to location



Photo # 4899 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Production Pad

Location ID: 456107



Photo # 4900 Location



Photo # 4901 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DOE 1-M-18 Production Pad

Location ID: 456107



**Photo # 4902 PRV vent line does not comply with CECMC pressure safety device rules**



**Photo # 4903 PRV vent line does not comply with CECMC pressure safety device rules**