

Inspection Photos  
Location Name: Trautman Farms 2-5  
API Number: 125-08898



1. Lease sign at well location.



2. View of wellhead. Note staining around wellhead.

Inspection Photos  
Location Name: Trautman Farms 2-5  
API Number: 125-08898



3. View of oil that has leaked from the gear box.



4. Additional view of oil leaking from gear box.

Inspection Photos  
Location Name: Trautman Farms 2-5  
API Number: 125-08898



5. Well location overview.



6. Lease sign at remote shared gathering location.

**Inspection Photos**  
**Location Name: Trautman Farms 2-5**  
**API Number: 125-08898**



**7. Gas meter inside remote meter shed.**



**8. Shared gathering location overview.**