

Inspection Photos
Location Name: Wagner 1-5
API Number: 125-08951



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Wagner 1-5
API Number: 125-08951



3. View of staining around pumping unit.



4. Lube oil on cement and soil at pumping unit gear box.

Inspection Photos
Location Name: Wagner 1-5
API Number: 125-08951



5. Well location overview.



6. Lease sign at remote shared gathering location.

Inspection Photos
Location Name: Wagner 1-5
API Number: 125-08951



7. Gas meter inside meter shed.



8. Remote shared gathering location overview.