

Final Reclamation and Stormwater Inspection

December 18, 2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 319319

Well Name: BBR ABBOTT FARMS #22-34

Inspection Document #: 718600107

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BBR ABBOTT FARMS #22-34
Location ID: 319319



Photo 1. ECMC drone imagery taken on 12/18/2024. Overview of well location (orange) and access road (red arrows). Open excavation is present at wellsite, access road has not been reclaimed. Green circle = the active Doris #12-34 well (API # 123-10420).

Inspection Photos
Location Name: BBR ABBOTT FARMS #22-34
Location ID: 319319



Photo 2. Looking across the wellsite. Well appears to be plugged and abandoned. Open excavation with improperly installed fences.



Photo 3. Soil has been placed on liners without proper stormwater BMPs. Concrete debris and trash are present.



Inspection Photos
Location Name: BBR ABBOTT FARMS #22-34
Location ID: 319319



Photo 4. Debris (tumbleweed) is present within the excavation. Metal pipe, possibly the well head is visible.



Photo 5. See photo 4 comments.



Inspection Photos
Location Name: BBR ABBOTT FARMS #22-34
Location ID: 319319



Photo 6. ECMC drone photo taken 12/18/2024 of wellsite.



Photo 7. T-posts possibly indicating location of buried flowline. Flowline abandonment verification has not been submitted.

