

Final Reclamation and Stormwater Inspection

December 18, 2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 464350

Well Name: Lone Eagle/13-34

Inspection Document #: 718600111

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lone Eagle/13-34
Location ID: 464350



Photo 1. ECMC drone imagery taken on 12/18/2024. Overview of tank battery location. Imagery illustrates equipment has not been removed and an open excavation is present near the northern separator.



Inspection Photos
Location Name: Lone Eagle/13-34
Location ID: 464350



Photo 2. Photo taken looking south at tank battery. Weedy annual vegetation is present throughout the location (Kochia, Russian Thistle). Surface equipment has not been removed.



Photo 3. Looking east at the tank battery. See Photo 2 comments.



Inspection Photos
Location Name: Lone Eagle/13-34
Location ID: 464350



Photo 4. Looking northwest at tank battery. Unmanaged weeds in secondary containment. Unused equipment remains on site.



Photo 5. Eastern tank has an open inspection hatch.

Inspection Photos
Location Name: Lone Eagle/13-34
Location ID: 464350



Photo 6. Picture taken from tank battery looking south. See Photo 2 comments.



Photo 7. Approximate 6'x10'x4' hole dug behind separator. Degraded construction fence remains but does not restrict access.

Inspection Photos
Location Name: Lone Eagle/13-34
Location ID: 464350




Photo 8. ECMC drone imagery taken 12/18/2024 of the excavation site. Stormwater BMPs are present around soil pile.



Photo 9. Inside of southern shed trash and stained soil is present.

