

# Interim Reclamation and Stormwater Inspection

December 16, 2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 470238

Well Name: CHAMPLIN 501 B/1

Inspection Document #: 718600114

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: CHAMPLIN 501 B/1  
Location ID: 470238



**Photo 1.** Photo taken looking south across tank battery. Weedy annual plant species are dominant (Kochia, Russian thistle).



**Photo 2.** Looking west across tank battery. See Photo 1 comments.





Inspection Photos  
Location Name: CHAMPLIN 501 B/1  
Location ID: 470238



**Photo 3.** Trash is present inside shed.



**Photo 4.** Gas leak from flagged pipe joint. Four gas monitor did not alarm.





Inspection Photos  
Location Name: CHAMPLIN 501 B/1  
Location ID: 470238



**Photo 5.** Appears to be unused equipment. Electrical boxes.



**Photo 6.** Looking west from tank battery location. See Photo 1 comments.

