

# Interim Reclamation and Stormwater Inspection

December 16, 2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 464916

Location Name: Dottie Doris/11,12-34

Inspection Document #: 718600090

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Dottie Doris/11,12-34  
Location ID: 464916



**Photo 1.** Photo taken from the north side of tank battery. Sign reads DOTTIE 11-33.



**Photo 2.** Looking south across tank battery. Undesirable annual vegetation is present throughout the location including Kochia and Russian thistle. This tank battery area is shared with Doris 12-34 (Loc 318979)



Inspection Photos  
Location Name: Dottie Doris/11,12-34  
Location ID: 464916



**Photo 3.** Picture taken east of tank battery looking west. Uncapped pipes and trash are present on location.



**Photo 4.** Photo taken from east of tank battery looking northwest. Groundwater monitoring wells are present in this area.

