

Final Reclamation and Stormwater Inspection

December 16, 2024

Operator: P O & G OPERATING LLC - 10635

Location ID: 427114

Well Name: Bosky PC/Z22-14 Tank

Inspection Document #: 718600120

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Bosky PC/Z22-14 Tank

Location ID: 427114



Photo 1. Photo taken looking north across tank battery. Undesirable weedy annual plant species are present throughout location. (Kochia, Russian thistle).



Photo 2. Looking east across tank battery. Trash is present on location.



Inspection Photos

Location Name: Bosky PC/Z22-14 Tank

Location ID: 427114



Photo 3. Looking south across location. See Photo 1 comments.



Photo 4. Looking north at produced water tank. Bucket of oil and broken glass remain on site.



Inspection Photos
Location Name: Bosky PC/Z22-14 Tank
Location ID: 427114



Photo 5. Stained soil at joint between produced water tank and separator.



Photo 6. Produced water tank with no secondary containment.

