

Interim Reclamation and Stormwater Inspection

December 16, 2024

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 318936

Well Name: OPAL #14-34 (1)

Inspection Document #: 718600088

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: OPAL #14-34 (1)
Location ID: 318936



Photo 1. Photo taken looking west from tank battery. Weedy annual vegetation is dominant throughout site including Kochia and Russian thistle.



Photo 2. Photo looking east from tank battery. List B noxious weed Scotch thistle is present on location.



Inspection Photos
Location Name: OPAL #14-34 (1)
Location ID: 318936



Photo 3. Looking at east side of tank battery. Partially buried vessels sign is degraded and cap is removed allowing wildlife access.



Photo 4. Photo taken west side of tank battery. Warning label is degraded. See Photo 1 comments.



Inspection Photos
Location Name: OPAL #14-34 (1)
Location ID: 318936



Photo 5. Inside separator building. Trash and debris are present.



Photo 6. Uncapped pipe at tank battery location.



Inspection Photos
Location Name: OPAL #14-34 (1)
Location ID: 318936



Photo 7. Locations of unfilled potholes potentially related to location of buried flowline.



Photo 8. Pothole near tank battery. Approximately 2 ft deep.

Inspection Photos
Location Name: OPAL #14-34 (1)
Location ID: 318936



Photo 9. Pothole at midpoint approximately 3 ft deep near degraded underground gas line sign.



Photo 10. Wellhead location. No fencing to exclude livestock was present around wellhead.

