

# Interim Reclamation and Stormwater Inspection

December 16, 2024

Operator: P O & G OPERATING LLC - 10635

Location ID: 427113

Well Name: Bosky PC #Z22-14

Inspection Document #: 718600122

Weld County, CO

Anthony Dunnam  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bosky PC #Z22-14  
Location ID: 427113



**Photo 1.** Photo taken looking north across well site.



**Photo 2.** Pumpjack appears to be partially dismantled and unused equipment is left on site.





Inspection Photos  
Location Name: Bosky PC #Z22-14  
Location ID: 427113



**Photo 3.** Fencing is not installed around pump. Undesirable annual plant species are present (Kochia).



**Photo 4.** Barrel does not have label. Chemicals stored out of secondary containment.

