

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404040393

Date Received:

12/26/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001451

Inspection Date: 11/05/2024

FIR Submit Date: 11/13/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 312036

Location Name: BELLINO GAS UNIT-M34N8W Number: 30NWNW County: _____

Qtrqtr: NWN Sec: 30 Twp: 34N Range: 8W Meridian: M
W

Latitude: 37.168362 Longitude: -107.765024

FACILITY - API Number: 05-067- -00 Facility ID: 312036

Facility Name: BELLINO GAS UNIT-M34N8W Number: 30NWNW

Qtrqtr: NWN Sec: 30 Twp: 34N Range: 8W Meridian: M
W

Latitude: 37.168362 Longitude: -107.765024

CORRECTIVE ACTIONS:

2 CA# 200404

Corrective Action: Comply with rule 606, remove and properly dispose of trash.

Date: 11/20/2024

Response: CA COMPLETED

Date of Completion: 12/26/2024

Operator
Comment:

Trash has been removed.

ECMC Decision: _____

Date:

Date of Completion: 12/26/2024

Weeds have been removed.

ECMC Decision: _____

Comment:	Corrective actions for weeds and trash removal have been completed. See attachment for photos.
----------	--

Signed:

Date: 12/26/2024 10:27:27 AM

<u>Document Number</u>	<u>Description</u>
404040393	FIR RESOLUTION SUBMITTED
404040394	Bellino 1,3 CA photos

Page 2 of 2