

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404040439

Date Received:

12/26/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001450

Inspection Date: 11/05/2024

FIR Submit Date: 11/13/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325927

Location Name: PICCOLI GAS UNIT A-M34N9W Number: 23SWSE County: _____

Qtrqr: SWSE Sec: 23 Twp: 34N Range: 9W Meridian: M

Latitude: 37.169807 Longitude: -107.792396

FACILITY - API Number: 05-067-00 Facility ID: 325927

Facility Name: PICCOLI GAS UNIT A-M34N9W Number: 23SWSE

Qtrqr: SWSE Sec: 23 Twp: 34N Range: 9W Meridian: M

Latitude: 37.169807 Longitude: -107.792396

CORRECTIVE ACTIONS:

1 CA# 200418

Corrective Action: Comply with rule 606, remove and properly dispose of debris.

Date: _____

Response: CA COMPLETED

Date of Completion: 12/24/2024

Operator Comment: Weedy debris has been removed.

ECMC Decision: _____

Weedy debris has been removed.

Seeded cut slope and reestablished runoff drainage

Corrective Actions have been completed. See attachment for photos

Date: 12/26/2024 10:31:44 AM

Total Attach: 2 Files