



PHOTOGRAPHIC LOG

QB LLC	SGV 1K Ramos 896 1-23A – Facility Decommissioning	31406292.022
---------------	--	---------------------

Photo No.	Date	
9	12/10/2024	
Overview of stockpile aliquot collection using the excavator View south		