

Inspection Photos
Location Name: QB Energy RULISON FEDERAL 1-13 (RM1) Pad
Location #: 334667



Photo # 4732 From Entrance to location



Photo # 4733 Location



Inspection Photos
Location Name: QB Energy RULISON FEDERAL 1-13 (RM1) Pad
Location #: 334667



Photo # 4734 Location



Photo # 4735 Location

Inspection Photos
Location Name: QB Energy RULISON FEDERAL 1-13 (RM1) Pad
Location #: 334667




Photo # 4736 Location



Photo # 4737 Location

Inspection Photos

Location Name: QB Energy RULISON FEDERAL 1-13 (RM1) Pad

Location #: 334667



Photo # 4738 Location



Photo # 4739 Location



Inspection Photos

Location Name: QB Energy RULISON FEDERAL 1-13 (RM1) Pad

Location #: 334667



Photo # 4740 Hole in liner/liner needs maintenance



Photo # 4741 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: QB Energy RULISON FEDERAL 1-13 (RM1) Pad

Location #: 334667



Photo # 4742 Holes in liner/liner needs maintenance



Photo # 4743 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: QB Energy RULISON FEDERAL 1-13 (RM1) Pad

Location #: 334667



Photo # 4744 Hole in liner/liner needs maintenance



Photo # 4745 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: QB Energy RULISON FEDERAL 1-13 (RM1) Pad

Location #: 334667



Photo # 4746 Hole in liner/liner needs maintenance



Photo # 4747 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: QB Energy RULISON FEDERAL 1-13 (RM1) Pad

Location #: 334667



Photo # 4748 Open ended load line