

Inspection Photos
Location Name: AB35-11/Pad
Location #: 422514



Photo #1
Cecil USX AB35-11D (123-33294) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 15 yds.



Photo #2
Cecil USX AB35-11D, AB35-12D, AB 35-14,
Dyer - USX AB 35-13
Battery site
Abandoned: ALL Equipment Removed
Plugged & Abandoned | PA (4-Wells)
prior photo

