

Inspection Photos

Location Name: CECIL USX AB-67N64W/35SESW

Location #: 302231



Photo #1

Cecil USX AB 35-14 (123-27389) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 150 yds.



Photo #2

Cecil USX AB35-11D, AB35-12D, AB 35-14,

Dyer - USX AB 35-13

Battery site

Abandoned: ALL Equipment Removed

Plugged & Abandoned | PA (4-Wells)

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources