

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/27/2024

Submitted Date:

12/28/2024

Document Number:

707603447**FIELD INSPECTION FORM**

Loc ID 422514	Inspector Name: Evins, Bret	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 5 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: <u>100322</u> Name of Operator: <u>NOBLE ENERGY INC</u> Address: <u>1099 18TH STREET SUITE 1500</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422510	WELL	PA	06/12/2023	OW	123-33291	CECIL USX AB35-12D	RI

General Comment:

This is a **PLUGGED & ABANDONED WELL / RECLAMATION** inspection.
 This is a Final Reclamation Inspection for PA Well API# 123-33291, on an active location.
 Well(s) was / were Plugged & Abandoned | PA on 06/12/2023.
 Well(s): 1: Plugged & Abandoned | PA.
 Battery: Abandoned. ALL equipment removed.
 Abandoned Battery SE corner GPS coordinates: 40.526480 / -104.523320

Abandoned Centralized Battery formerly served 3 Location IDs
 (422514, 302231, 306371).
 (Well(s): 4: Plugged & Abandoned | PA).

Reference (Associated Well(s) Inspections):
 A.) Field Inspection Report doc. #707603445 and/or Location ID #422514
 for PA Well(s) info.
 B.) Field Inspection Report doc. #707603447 and/or Location ID #422514
 for PA Well(s) info.
 C.) Field Inspection Report doc. #707603449 and/or Location ID #302231
 for PA Well(s) info.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:

Type: Plunger Lift	# 0		corrective date
Comment:		Plugged & Abandoned PA. Equipment removed.	
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	422510	Type:	WELL	API Number:	123-33291	Status:	PA	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IMPROVED PASTURE, IRRIGATED

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IMPROVED PASTURE, IRRIGATED _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: **Operator has PLUGGED & ABANDONED | PA the above well(s) on an active location; therefore, this is a well release on an active location. This inspection confirms that eight (8) well(s) remain at the location. The 8 wells have been drilled and are idle awaiting frac. Refer to the attached inspection photo(s).**

Corrective Action:		Date	
Overall Final Reclamation	Pass	Well Release on Active Location <input checked="" type="checkbox"/>	Multi-Well Location <input checked="" type="checkbox"/>

ECMC Comments		
Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On FRI 12/27/2024 at approximately 12:07 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: NOBLE ENERGY INC Location Name: AB35-11/Pad Location ID: 422514 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. and/or photo(s) #1 attached to this report. Location County: Weld County, Colorado Weather: Partly Sunny, dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Abandoned. ALL equipment removed. Abandoned Battery SE corner GPS coordinates: 40.526480 / -104.523320</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Form 6-SRA on file. Plugging, cut/cap date: 06/12/2023. Approved. Plugged & Abandoned PA well GPS coordinates: 40.529380 / -104.522100</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	12/28/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603448	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6855686