

Inspection Photos

Location Name: TORRES-USX AB-67N64W/35NESE

Location #: 306365




Photo #1

Torres-USX AB 35-9 (123-24538) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 15 yds.



Photo #2

Torres-USX AB 35-9, GARCIA USX AB 35-10D, 35-23

Battery site

Abandoned: ALL Equipment Removed

Plugged & Abandoned | PA (3-Wells)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources