

Inspection Photos
Location Name: GARCIA USX AB/35-23
Location #: 422237



Colorado Energy & Carbon Management Commission
Weld County
+40.527167, -104.512646
191° S
2024-12-27 12:31

Photo #1

Garcia USX AB 35-10D (123-33201) Wellsite

Plugged & Abandoned | PA

Cut / Capped

~ 10 yds.



Colorado Energy & Carbon Management Commission
Weld County
+40.529759, -104.507879
190° S
2024-12-27 12:40

Photo #2

Torres-USX AB 35-9, GARCIA USX AB 35-10D, 35-23

Battery site

Abandoned: ALL Equipment Removed

Plugged & Abandoned | PA (3-Wells)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources