

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/27/2024

Submitted Date:

12/28/2024

Document Number:

707603453

**FIELD INSPECTION FORM**

Loc ID 422237 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

4 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422230	WELL	TA	10/24/2022	OW	123-33201	GARCIA USX AB 35-10D	PA

**General Comment:**

Well(s): 1: Plugged & Abandoned | PA.  
Battery: Abandoned. ALL equipment removed.  
Abandoned Battery SE corner GPS coordinates: 40.529251 / -104.507955

Abandoned Centralized Battery formerly served 2 Location IDs (306365, 422237).  
(Well(s): 3: Plugged & Abandoned | PA).

Reference (Associated Well(s) Inspections):  
A.) Field Inspection Report doc. #707603451 and/or Location ID #306365 for PA Well(s) info.  
B.) Field Inspection Report doc. #707603453 and/or Location ID #422237 for PA Well(s) info  
C.) Field Inspection Report doc. #707603455 and/or Location ID #422237 for PA Well(s) info.



**Inspected Facilities**Facility ID: 422230 Type: WELL API Number: 123-33201 Status: TA Insp. Status: PA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><b>CECMC Inspection Report Synopsis:</b></p> <p>On FRI 12/27/2024 at approximately 12:31 hrs. I, Bret Evins, conducted an onsite inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: GARCIA USX AB/35-23  Location ID: 422237  Well Name(s) &amp; API:  Reference:  See "Inspected Facilities" section on page 1 of this Field Inspection Report. and/or photo(s) #1 attached to this report.  Location County: Weld County, Colorado  Weather: Partly Sunny, dry.</p> <p>While there, I observed:  Well(s): 1: Plugged &amp; Abandoned   PA.  Battery: Abandoned. ALL equipment removed.  Abandoned Battery SE corner GPS coordinates: 40.529251 / -104.507955</p> <p><b>WELL STATUS COMMENT:</b>  Plugged &amp; Abandoned   PA.  Form 6-SRA on file. Plugging, cut/cap date: 10/31/2024. Approval Pending.  Plugged &amp; Abandoned   PA well GPS coordinates: 40.527124 / -104.512689</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	12/28/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603454	Site photo(s)	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6855711">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6855711</a>