

Inspection Photos

Location Name: PETTINGER-USX AB-67N64W/35SENE

Location ID: 306362



Photo #1

Pettinger-USX AB 35-8 (123-24535) Wellsite
Temporarily Abandoned | TA



Photo #2

Pettinger-USX AB 35-8 Wellsite
Temporarily Abandoned | TA
Wellsite, Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PETTINGER-USX AB-67N64W/35SENE

Location ID: 306362



Photo #3

Pettinger USX AB 35-8, 35-01D Battery site

Inactive | Shut-down

Formerly served:

Pettinger USX AB 35-02, 35-7;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 306362



Photo #4

Pettinger USX AB 35-8, 35-01D Battery site

Inactive | Shut-down

Battery site entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources