

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Photo # 5414 From entrance to location



Photo # 5415 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Photo # 5416 Location



Photo # 5417 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Photo # 5418 Location



Photo # 5419 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Dec 24, 2024 at 12:43:39 PM  
CO

Photo # 5420 Location



Dec 24, 2024 at 12:45:44 PM

Photo # 5421 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Photo # 5422 Location



Photo # 5423 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328




Photo # 5424 Location



Photo # 5425 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Dec 24, 2024 at 12:48:56 PM  
CO

Photo # 5426 Location



Dec 24, 2024 at 1:05:03 PM  
CO

Photo # 5427 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Photo # 5428 Location



Photo # 5429 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Photo # 5430 Location



Photo # 5431 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Photo # 5432 Staining in secondary containment



Photo # 5433 Staining near tank battery



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Photo # 5434 Open ended load line




Photo # 5435 Battery sign weathered & illegible/does not comply with CECMC rules



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Photo # 5436 Debris



Photo # 5437 Debris



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Photo # 5438 Debris



Photo # 5439 Debris

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 23-5 Pad

Location ID: 383328



Photo # 5440 Debris



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources