

Inspection Photos

Location Name: LANG-USX AB-67N64W/35SENW

Location ID: 306370



Colorado Energy & Carbon Management Commission
Weld County
+40.531184, -104.519283
334° NW
2024-12-27 14:39

Photo #1

Lang-USX AB 35-6 (123-24546) Wellsite

Plugged & Abandoned | PA

Not cut / capped



Colorado Energy & Carbon Management Commission
Weld County
+40.536846, -104.520007
113° SE
2024-12-27 14:54

Photo #2

Lang USX AB 35-03, 35-19D, 35-05D Battery site

Inactive | Shut-down

Formerly served:

Lang-USX AB 35-6;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 422547



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: LANG-USX AB-67N64W/35SENW

Location ID: 306370



Photo #3

Lang USX AB 35-03, 35-19D, 35-05D Battery site

Inactive | Shut-down

Well(s), Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources