

Inspection Photos

December 20th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326675

Inspection Document #: 714001622

La Plata County, CO

Township: NWSW 2 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO


**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Paisley 2
Location ID: 326675



Photo 1. View of well pad taken from the access point facing center.



API #: 067-08675



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Paisley 2
Location ID: 326675

12/20/24
202° S



Photo 2. Woody debris have been removed from separator equipment.

Inspection Photos
Location Name: Paisley 2
Location ID: 326675

12/20/24
63° NE



Inspection Photos
Location Name: Paisley 2
Location ID: 326675



Photo 4. Reference area composed of Smooth Brome and Sand Dropseed.