

Inspection Photos

December 20th, 2024

Operator: Simcoe LLC - 10749

Location ID: 326618

Inspection Document #: 714001623

La Plata County, CO

Township: SESW 1 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Neva Dove A2
Location ID: 326618



Photo 1. View of well pad taken from the access point facing center.



API #: 067-08412



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Neva Dove A2
Location ID: 326618



Photo 2. Weedy Kochia and Russian Thistle debris observed lining the western and northern perimeter fence.