

# Inspection Photos

December 20th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306841

Inspection Document #: 714001624

La Plata County, CO

Township: NWNE 14 34N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Snooks A2  
Location ID: 306841



12/20/24  
127° SE



12/20/24  
179° S

Photo 1. View of well pad taken from the access point facing center.



Inspection Photos  
Location Name: Snooks A2  
Location ID: 306841

12/20/24  
47° NE



**Photo 2.** View of surface owner equipment, trailers and trash observed on location.

Inspection Photos  
Location Name: Snooks A2  
Location ID: 306841



**Photo 3.** Knapweed observed on location.

Inspection Photos  
Location Name: Snooks A2  
Location ID: 306841

12/20/24  
324° NW



**Photo 4.** Impacted surface material observed at the well head.