

# Inspection Photos

December 20th, 2024

Operator: Simcoe LLC - 10749

Location ID: 334242

Inspection Document #: 714001626

La Plata County, CO

Township: NESE 8 34N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Emma McCarty A1, 3  
Location ID: 334242



Photo 1. View of wellhead assembly.

Inspection Photos  
Location Name: Emma McCarty A1, 3  
Location ID: 334242



Photo 2. View of surface owner equipment stored on location.

Inspection Photos  
Location Name: Emma McCarty A1, 3  
Location ID: 334242




**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Stormwater BMPs have been installed in the southern interim reclamation areas.

API #: 067-07856, 09334

Inspection Photos  
Location Name: Emma McCarty A1, 3  
Location ID: 334242



**Photo 4.** Separator and Produced water tank signs/placards are starting to deteriorate, future maintenance is advised.