

Inspection Photos

December 20th, 2024

Operator: Simcoe LLC - 10749

Location ID: 306905

Inspection Document #: 714001627

La Plata County, CO

Township: SWSW 9 34N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: French 01-9U 2R
Location ID: 306905

12/20/24
185° S



Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: French 01-9U 2R
Location ID: 306905



Photo 2. Treatment efforts for Musk Thistle on location appear successful. Evidence that Musk Thistle had flowered and gone to seed this season were observed.

Inspection Photos
Location Name: French 01-9U 2R
Location ID: 306905



12/20/24
332° NW

