

Inspection Photos

December 20th, 2024

Operator: Simcoe LLC - 10749

Location ID: 333472

Inspection Document #: 714001629

La Plata County, CO

Township: NWSE 16 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Couch 01-16U 2, 3, 4
Location ID: 333472

12/20/24
227° SW




Photo 1. View of well pad taken from the access point facing center.

Inspection Photos
Location Name: Couch 01-16U 2, 3, 4
Location ID: 333472

12/20/24
237° SW



Photo 2. Produced water signs/placards are deteriorating and no longer displaying capacity.

Inspection Photos
Location Name: Couch 01-16U 2, 3, 4
Location ID: 333472



Photo 3. Stormwater appears controlled on the location.