

Inspection Photos

December 20th, 2024

Operator: Simcoe LLC - 10749

Location ID: 334249

Inspection Document #: 714001632

La Plata County, CO

Township: SWNE 18 34N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Beaver Creek B2
Location ID: 334249



12/20/24
258° W

Photo 1. View of well pad taken from the access point facing center.



12/20/24
229° SW

Inspection Photos
Location Name: Beaver Creek B2
Location ID: 334249

12/20/24
239° SW



Inspection Photos
Location Name: Beaver Creek B2
Location ID: 334249



Photo 3. Impacted material at well head and pump jack muffler.

Inspection Photos
Location Name: Beaver Creek B2
Location ID: 334249



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Metal panel/trash observed on the northern edge of the disturbance.

API #: 067-08214