

**Inspection Photos**  
**Location Name:UPRR\_23\_PAN\_AM\_M3**  
**Location ID: 320062**



**Photo #1 Tank(East side of berm) & weeds.**




**Photo #2 Tank (West side of berm) & weeds.**

**Inspection Photos**  
**Location Name:UPRR\_23\_PAN\_AM\_M3**  
**Location ID: 320062**



**Photo #3 Separator (appears to have been moved to the East side of location).**



**Photo #4 Meter, unmarked risers & weeds.**



Inspection Photos  
Location Name:UPRR\_23\_PAN\_AM\_M3  
Location ID: 320062



Photo #5 Meter, unmarked risers & weeds.




Photo #6 Unmarked risers & weeds.

**Inspection Photos**  
**Location Name: UPRR\_23\_PAN\_AM\_M3**  
**Location ID: 320062**



**Photo #7 Well head & weeds.**