

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, VALLEY FARMS-66S92W/15NENW

Location ID: 335534

Date: 12/23/2024



Dec 23, 2024 at 13:15:20  
535-571 Mineota Dr  
Silt CO 81652  
United States

Location Overview – Photo #05585



Dec 23, 2024 at 13:17:13  
535-571 Mineota Dr  
Silt CO 81652  
United States

Location – Photo #05586

## Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, VALLEY FARMS-66S92W/15NENW

Location ID: 335534

Date: 12/23/2024



Location – Photo #05592



Location – Photo #05588




## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, VALLEY FARMS-66S92W/15NENW

Location ID: 335534

Date: 12/23/2024



Location – Photo #05598



Location – Photo #05605

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, VALLEY FARMS-66S92W/15NENW

Location ID: 335534

Date: 12/23/2024



Stored Supplies – Photo #05606



Stored Supplies – Photo #05607

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, VALLEY FARMS-66S92W/15NENW

Location ID: 335534

Date: 12/23/2024



**Wildlife Entry Hazard – Photo #05593**

