

**Operator: *Extraction Oil & Gas Inc.***

**Location Name: EATON CATTLE CO.-64N66W 18NESE**

**Loc ID: 319190**

**Inspection: 697010524**



**Exhibit A**

**CA:** Trash has been placed on location, see attached photo. Comply with Rule 606.

**CA Resolution:** Operator has addressed the CA issue, trash has been picked up in order to comply with Rule 606.