

Inspection Photos

Location Name: OWL CREEK-67N64W/31SWSW

Location ID: 322723



Photo #1

Owl Creek #9 (123-11935) Wellsite

Plugged & Abandoned | PA

Not cut / capped



Photo #2

Owl Creek #9 Battery site

Inactive | Shut-down

Formerly served:

Owl Creek #9;

Plugged & Abandoned | PA

Equipment Documented; Loc ID: 322723



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: OWL CREEK-67N64W/31SWSW

Location ID: 322723



Photo #3

Owl Creek #9 Battery site

Inactive | Shut-down

Well(s), Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources