

Inspection Photos

Location Name: OWL CREEK-67N64W/31SWSW

Location ID: 322723



Photo #1

Owl Creek #9 Battery site

Inactive | Shut-down

Well(s)ite(s), Battery entrance



Photo #2

Owl Creek #9 Battery site

Inactive | Shut-down

Formerly served:

Owl Creek #9;

Plugged & Abandoned | PA



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: OWL CREEK-67N64W/31SWSW

Location ID: 322723



Photo #3

Owl Creek #9 Battery site

Inactive | Shut-down

Crude oil, produced H2O tank(s): SE corner



Photo #4

Owl Creek #9 Battery site

Inactive | Shut-down

ECD(s), Separator(s)



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: OWL CREEK-67N64W/31SWSW
Location ID: 322723



Photo #5
Owl Creek #9 Battery site
Inactive | Shut-down
Battery sign



Inspection Photos

Location Name: OWL CREEK-67N64W/31SWSW

Location ID: 322723

Associated Well(s)	API	Status
1. Owl Creek #9	123-11935	PA

Photo #6

Owl Creek #9 Battery site

Inactive | Shut-down

Associated Well(s): *Former*

1: Plugged & Abandoned | PA



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources