

## Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY 127-3 Pad

Location # 324083



Photo # 5923 From entrance to location




Photo # 5924 Location

# Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY 127-3 Pad

Location # 324083



Photo # 5925 Location




Photo # 5926 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY 127-3 Pad

Location # 324083



Photo # 5927 Location



Photo # 5928 Location

## Inspection Photos

Location Name: TEP Rocky Mountain LLC MACKLEY 127-3 Pad

Location # 324083



**Photo # 5929 Netting/wildlife protection needs maintenance/wildlife hazard**