

# Inspection Photos

API: 071-06288

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 12/31/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos




**Photo 2.** Facing toward the wellhead. There is whitened material around the wellhead possibly from a leaking wellhead.





## Inspection Photos



**Photo 3.** Facing northeast at the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 4.** Facing toward the produced water pit.

