

Inspection Photos

API: 071-06293

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 12/31/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



December 31, 2024
+37.218319,-104.825026
Las Animas County
ECMC

Photo 1. Facing northwest toward the wellsite.



Inspection Photos



Photo 2. Facing west at the location. The black polyline transfers water to offsite pit.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06293 | Date: 12/31/2024

Inspection Photos



Photo 3. Facing southwest at the location.



Inspection Photos



Photo 4. Facing toward the offsite produced water pit.

