

Inspection Photos

API: 071-08483

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 12/31/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along the access road. This area has will need stormwater maintenance..



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Facing northwest toward the wellsite.



Inspection Photos



Photo 3. Facing southeast at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing northeast at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources