

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6NWNE

Location ID: 334920

Date: 12/30/2024



Location – Photo #05654



Location – Photo #05657

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6NWN

Location ID: 334920

Date: 12/30/2024



Location – Photo #05658



Damaged and Illegible Wellhead Sign – Photo #05656



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PA-67S95W/6NWNE

Location ID: 334920

Date: 12/30/2024



Lack of Stabilization – Photo #05660



Insufficient Tracking BMPs – Photo #05659