

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GV-67S95W/5NWNW

Location ID: 334627

Date: 12/30/2024



Location Overview – Photo #05662



Location – Photo #05663



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GV-67S95W/5NWNW

Location ID: 334627

Date: 12/30/2024



Location – Photo #05666



Location – Photo #05667



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GV-67S95W/5NWNW

Location ID: 334627

Date: 12/30/2024



Open Wellhead Cellar – Photo #05664



Open Wellhead Cellar – Photo #05665